

The Corporate Business Division I Marine Department

Storage Questionnaire

Dear Sir/Madam,

General

This questionnaire enables us to assess the exposure to risks existing in your warehouse/site/location. Please fill it in with as many details as possible.

Thank you in advance for your co-operation.

Name of Assured Edushape Group Itd.
Address of warehouse/site/location 3 rd floor, building A-2, Haixiang Industrial Park, No. 3, Lijing North Road, Shenzhen Export Processing Zone, Pingshan District, Shenzhen City, P.R.China Details of contact person: Tel / Fax / E-mail Gil Mintz / gmintz@edushape.com
Construction:
Total area 6000 square meter Total height 3.8 meter/floor Internal separations walls
Type of construction (Light/Massive/steel frame):Massive
Walls (insulated panels, concrete blocks, wood, steel sheets): concrete blocks
Ceilings/Roofs (insulated panels, concrete, wood, steel sheets): concrete
Structure type (Combustible/Non-combustible/Fire resistive): Non-combustible
Stock:
Description of stock contents in details (Food and beverage, textile, electric and home electronics, raw materials, spare parts, machinery etc.): toys / game / packaging / part of toys
Type of stock (dangerous materials, flammable liquids, poisonous gases): toys and games from different materials (plastic, wood, foam etc.)
Packaging (Plastic containers, cardboard boxes, shrink encapsulated): All the option
Storage arrangement (Metal shelves/racks, wood/plastic pallets, open-top containers): wood/plastic pallets
Whilst in storage, are the goods being: labeled, re-labeled, sorted, re-sorted, packed, re-packed and/or undergoing any other process?The items come_labeled, part_will re-labeled, part come packed, part will re-packed Security: against burglary/breaking-in
Site circumference fencing: <u>12000meters</u> Entrance gates: <u>2</u>

Alarm system (Detectors type: passive, active, beam. Siren/flashing lamp): Siren



The Corporate Business Division I Marine Department

Guarding on site (24/7 Hrs, patrolling with stamping points for control): 24/7 Hrs
Type of locking all external doors (Internally, externally, type of locks): externally, 304 stainless steel
CCTV system installed on site (No. of cameras, monitor's location): 48, monitor room
Fire fighting measures
Sprinkler protection (water tank, water pumps, comply with NFPA-13): <u>water pumps, comply</u> with NFPA-13
Smoke detection system (connection to security centre): Yes, connected to Security Center
Smoke removal (blowers, windows): both blowers and windows
Portable measures (extinguishers, hydrants and hoses, hose reels): <u>extinguishers, hydrants</u> and hoses, hose reels
Public fire brigade (distance and time of arrival): 3KM, 10 minutes
Smoking policy on site (prohibited on site/within warehouse only): prohibited within WH only
Hot Work permit / Sub contractors permit implemented on site: Hot Work permit(No), Sub contractors permit implemented on site(yes)
Emergency Organization (trained and equipped teams, procedures): <u>trained and equipped</u> <u>teams (No), procedures (Yes)</u>
Fork lifts (Electric or diesel driven, electric chargers location): <u>Electric folk lifts, Charge location:</u> unloading platform on first floor of the building
Electric panels (Auto-gas extinguishing, Infra-red scanning): No
Natural Perils
Flood- vicinity to (River, coast, stream-distance and elevation): River:4KM, coast, 15KM
Windstorm (Height above sea level, open wind exposed plane): Height above sea level 45m
Snow accumulation on the roof: No snow
Site description and major neighborhood details:
Location – general description of the area zone (industrial, hi-tech, logistic): industrial and logistic area

Neighborhood - description of adjacent buildings/companies - engaged with: Logistics and customs service



The Corporate Business Division I Marine Department

is the site used by the assured only of is it used in addition by other companies?
used in addition by other companies
Sum Insured
<u>Julii ilisureu</u>
Maximum stock sum Insured (US\$ / €): \$500,000
This form should be accompanied with a picture of the warehouse
Loss record for the last 5 years:
Warehouse owner name, stamp & signature: Date:
Assured's name, stamp & signature: Date: